

# MX-5 Cup Technical Bulletin 02-09



**To:** SCCA Pro Racing MX-5 Cup Participants  
**From:** Jim Jess, MX-5 Technical Manager  
Phone: Office: (785) 862-7157 Cell: (785) 554-7904  
E-Mail: jjess@sccapro.com  
**Date:** April 15, 2009  
**Regarding:** Inner Fender Liners



---

**Effective Date:** Immediately

**3.6.6.9:** Left and Right inner fender liners must remain intact. Inner fender liners may be riveted in place and a small portion of the liners may be trimmed away where the tire makes contact with the inner fender liners. A template will be made available by Mazdaspeed. Left and right front fender liners may be removed only if the large excess holes are closed off using .040" - .060" aluminum and securely fastened into place using rivets .